

## Review Form 1.6

Journal Name:	<a href="#">Asian Journal of Medical Principles and Clinical Practice</a>
Manuscript Number:	Ms_AJMPCP_81410
Title of the Manuscript:	Analysis of Quality control of some fixed and portable X- ray units in Maharishi Markandeshwar Hospital India.
Type of the Article	Original Research Article

### General guideline for Peer Review process:

This journal's peer review policy states that **NO** manuscript should be rejected only on the basis of '**lack of Novelty**', provided the manuscript is scientifically robust and technically sound. To know the complete guideline for Peer Review process, reviewers are requested to visit this link:

(<https://www.journalajmpcp.com/index.php/AJMPCP/editorial-policy> )

### PART 1: Review Comments

	Reviewer's comment	Author's comment (if agreed with reviewer, correct the manuscript and highlight that part in the manuscript. It is mandatory that authors should write his/her feedback here)
<b>Compulsory</b> REVISION comments	<p><b>1) Abstract please divide in different section.</b></p> <p><b>2)</b> Therefore, in view of the above fact a study has been done to check the quality assurance of all the technical parameters of the stationary and portable X-ray equipment's available in the radiology department at MMIMSR, Mullana, Ambala, Haryana.</p> <p><b>3) Discussion:</b> There are a number of reasons for developing quality assurance programs in dental radiography. Prior to 1974, there were no requirements for machine performance[14] and the operating stability of many x-ray generators in use today is uncertain. Studies have shown that there are a variety of types of machine malfunction which may occur as a result of use and aging [15.16] . There is evidence to suggest that sight development is a common practice used to compensate for inadequate machine performance, inadequate operator training, or defective processing chemistry. Please insert here the most important results of the study</p> <p><b>4) Conclusion:</b> From the findings of the study concluded that all the X- ray machines placed in room 1, 2, 3, 4, 5, 6 and 7 in the Radiology department at Maharishi Markandeshwar Hospital, Mullan, Ambala, Haryana are in good quality and ensure their proper functioning. Please improve this section.</p>	
<b>Minor</b> REVISION comments	None	
<b>Optional/General</b> comments	None	

[Review Form 1.6](#)

**PART 2:**

	Reviewer’s comment	Author’s comment <i>(if agreed with reviewer, correct the manuscript and highlight that part in the manuscript. It is mandatory that authors should write his/her feedback here)</i>
Are there ethical issues in this manuscript?	<i>(If yes, Kindly please write down the ethical issues here in details)</i>	